# LuxaCrown Quick Guide

Impression-taking → Preparation → Optimization of the impression → Fill and place into position 0-30 seconds

Removal: 1:30-2:20 minutes → Finishing: After 5:00 Minutes → Surface processing and polishing → Permanent or temporary cementation → Placement → Timing: 5 minutes (filling/placing to finishing)